

Dry Gas Pipeline

Client Name and Location: Pipeline Operator – Taft, CA

Date of Application: October 2014

Mascoat Representative: Travis Creech

Applicator: Dunkin and Bush

Coating Used: Mascoat Industrial-DTI

Application: Dry Gas Pipeline

Dimensions: 10 small areas

Reason for Application: Repair Existing Coating

Mils Applied: 20 mils (0.5 mm)

Time to Complete: 1 day

Application Notes: This was a 2.5 mile pipeline that was coated with Mascoat Industrial-DTI in 2013. There were several spots that went across a right-of-way and had been damaged by someone dragging equipment across the pipe. The company wanted to make repairs for aesthetic reasons, so Mascoat was contacted. The repairs were very simple; after a normal SP-1 cleaning, the contractor used a Small Application Sprayer supplied by Mascoat to reapply in the damaged area.

Quote from end user and/or applicator: "We have DOT inspections periodically, and we like for everything to look nice. It only cost a couple hundred bucks to make these repairs. Compared to what we have to do to repair other types of insulation, it was nothing. Thanks for the help."

